

5. PRINCIPAL STAFF SEEN:

Topic	Names of staff seen for each topic	Position
8.3.1,	[REDACTED]	AWE Burghfield [REDACTED]
8.3.2,	[REDACTED]	[REDACTED]
8.4.2	[REDACTED]	[REDACTED]
8.3.3	[REDACTED]	Project Manager, [REDACTED]
8.3.4		
8.3.5		

6. POINTS OF INTEREST TO OTHER SITES/SITE INSPECTORS

None.

7. SUMMARY

No planned compliance inspection was undertaken during this visit due to the flooding event that occurred at AWE Burghfield. Progress on recovery from this is ongoing. A number of project meetings were attended, and good progress was made in clarifying a number of issues and identifying ways forward.

[REDACTED]

8. REPORT

8.1 Planned Inspection

None carried out

8.2 Reactive Inspections

None carried out during this visit.

8.3 Licensee's Project Related Work

8.3.1 Meeting on Engineering Status of Plant Following Flood

I held a meeting with [REDACTED] the [REDACTED] and [REDACTED] the [REDACTED] to discuss recovery from the recent flooding at AWE Burghfield. [REDACTED] outlined the events of Friday 20<sup>th</sup> July, which is when the main flood occurred at site. Having isolated feeds to all of the switchboards, a preliminary visual inspection revealed that the majority of switchgear was above the [REDACTED]

flood level and so was not badly affected. However, condensation was visible in a number of units, which had the potential to cause problems. Having ensured that all switches were off at the main switchboard and there was no distribution load, a full examination of the electrical status of the plant was begun. Condensation in some of the fire detection panels led [REDACTED] to believe that false alarms could be a real problem and so he made the decision not to re-instate the system. Our ND Fire Surveyor, [REDACTED] has assessed this situation and is content that the substitute arrangements that AWE(B) put in place whilst the fire detection system was not operable were adequate (see TRIM reference 2007/178433). These arrangements included an increased fire watch and a review of the facility fire risk assessment. A team from Criticality Safety Group was also called in and confirmed the fact that the fissile inventory in the facility was such that the risk from criticality was incredible; hence the decision was taken not to use the battery back-up for the Criticality Incident Detection system.

[REDACTED] then provided me with an update of the current status of each of the buildings. Power had been restored to each of the main process buildings enabling lights and HVAC to be switched back on. In many cases, HVAC was only restored to assist with drying of the buildings. The status of Building \*\* was particularly important as it contained an inventory which needed to be recovered. Although full power was available, power was limited to that which was required for the recovery operation. The floor was inspected and declared to be in good condition by [REDACTED]. He advised me that the Civils DA had also undertaken an inspection; further discussion on the recovery of the inventory from this building is reported in 8.3.2 below.

The other building containing an inventory was considered to be a bit more problematic by [REDACTED] not from a nuclear safety point of view but rather from a Company point of view. This is because it contains a number of one-off items, for which the controlling mechanisms etc were all under water and so could have experienced significant damage. Although [REDACTED] believed that recovery of the inventory would not be compromised by any potential damage to these plant items, the recovery could potentially be more difficult than the other building. Again further discussion is reported in 8.3.2 below.

[REDACTED] described the way forward for the facility. He was working on a programme to ensure that all buildings have undergone at least a visual inspection. This will flush out the need to do more tests. A team led by [REDACTED] is working through the EMIT schedule. In general it is expected that most EMITs will still be within the tolerance specified in the relevant CSI. I was advised that if the maintenance extended outside the tolerance for whatever reason, then this would go through the 804 change control process. I advised [REDACTED] that as part of my inspections over the coming months I would ensure that the EMIT of all plant which may affect safety is undertaken in accordance with the arrangements under LC 28, especially those items which may have been affected during the event.

Overall, [REDACTED] believed that from a maintenance point of view, he did not believe that the flooding caused any major issues that may affect nuclear safety.

[REDACTED]



SITE INSPECTION REPORT No:

AWE 2007/061

Page 5 of 7

WHOLE PAGE REDACTED



[REDACTED]

NII Site Inspector  
August 2007

Distribution:

[REDACTED]

AWE Inspection Team

[REDACTED]

[REDACTED]