

~~Confidential~~



Abnormal Event Report

Form Ref. **09514339**
No.

Serious abnormal events shall be reported to the Aldermaston emergency organisation via ext 222. In other cases, other than minor abnormal events phone:	Site	Normal hours	Out of normal hours
	Aldermaston Burghfield	ATT ext. [redacted] ATT ext. [redacted]	Shift Manager ext. [redacted] Senior Shift Engineer ext. [redacted]

1. Time and place of abnormal event.					
Date 15/10/2009	Time 11:30	Precise location [redacted]	Building [redacted]	Facility [redacted]	SITE: Aldermaston
Facility Manager [redacted]	Contracting Company (if appropriate) [redacted]		Work Sup. Officer [redacted]	Area Type(s): Radiation / Contamination	
Abnormal Event Type Radiological	Security Manager Organisational Area	Abnormal Event Directorate DRAS			

2. Description of abnormal event (Give a detailed description of what happened, use these headings for guidance) a)Circumstances b)Abnormal event c)Effect d)Remedial action

A temperature excursion on [redacted] furnace was experienced. The furnace power was turned down and the FEC was contacted immediately. The lab was restricted and all relevant parties were made aware.

What assistance was called?
NONE

6. Details of witness(es).					
Name	Tel.	Bldg	Dir	Mgmt Area	Contracting Company
[redacted]	[redacted]	[redacted]	DRAS	MSRD	

7. Form completed by.						
Name	Tel.	Dir	Mgmt Area	Contracting Company	Date & Time	
[redacted]	[redacted]	DRAS	MSRD	AWE	15/10/2009 14:05:08	

~~Confidential~~

AWE SME Response to AE 09514339

Corrective action was to take [REDACTED] out of service.

[REDACTED] is currently off line awaiting completion of the Periodic Review of Safety (PRS) actions.

A category one shortfall has been identified against modern standards; with a shortfall action plan [REDACTED]/PRS/C1/AP/11 being in place to address a total of 8 recommendations in relation to the [REDACTED] process at [REDACTED]

All 8 recommendations are being tracked and managed on the [REDACTED] PRS shortfalls register.