

Incorrect isolation applied to fire panel

Menu ▾

Query

Event Summary: * Incorrect isolation applied to fire panel

Event Number: * 1-17VQJI

Originator: [REDACTED]

Owner: [REDACTED]

Assistance Called: [REDACTED]

Company Involved: [REDACTED]

Location - Project: * [REDACTED]

Precise Location: Lobby

Security / Sensitive: * Normal

Event Status: Closed

Date Occurred: 29/11/2011 12:30:4

Date Reported: 29/11/2011 16:27:4

Event Closed: 22/02/2012 09:35:4

INES Code: [REDACTED]

Case Name: Incorrect isolation appli

Investigator: [REDACTED]

Case Status: Case Closed

OSHA Code: [REDACTED]

OSHA Description: [REDACTED]

Injury:

Originators Description

During a spot check of the fire alarm panel status, fire zone 4 was found to be isolated.

Further Details

[REDACTED]

Current Status of Event

System is normal

Initial Assessment | Functional Coding | Injured Parties | Contacts | Cases | Attachments | Super User Notes | Audit Trail | External Reporting

Menu ▾

Query

Event Description

Originators Description: *

During a spot check of the fire alarm panel status, fire zone 4 was found to be isolated.

Further Details:

Originators Plant/Equipment Description: *

Fire alarm control panel.

Fire zones found to be isolated

Menu ▾ Query

Event Summary: * Fire zones found to be isolated

Event Number: * 1-UN7Y8

Originator: [REDACTED]

Owner: [REDACTED]

Assistance Called: [REDACTED]

Company Involved: [REDACTED]

Location - Project: * [REDACTED]

Precise Location: Main foyer

Security / Sensitive: * Normal

Event Status: Investigation Required

Date Occurred: 07/04/2011 11:00:4

Date Reported: 07/04/2011 11:41:4

Event Closed: [REDACTED]

INES Code: [REDACTED]

Case Name: Fire zones found to be i

Investigator: [REDACTED]

Case Status: Report Complete

OSHA Code: [REDACTED]

OSHA Description: [REDACTED]

Injury:

Originators Description

Fire detection system found to have two zones unexpectedly isolated; zone 4 and zone 5 for the controlled area and GF60 ('white' lab) respectively.

Further Details

[REDACTED]

Current Status of Event

Fire detections system proven to be fully operational

Initial Assessment | Functional Coding | Injured Parties | Contacts | Attachments | Super User Notes | Audit Trail | External Reporting

Menu ▾ Query

Event Description

Originators Description: * Fire detection system found to have two zones unexpectedly isolated; zone 4 and zone 5 for the controlled area and GF60 ('white' lab) respectively.

Further Details: [REDACTED]

Originators Plant/Equipment Description: [REDACTED] smoke detectors in zones above