

Reply to: RICC, Direct Dia

e-mail:

ONR 200-019 N

ONR Ref:



Aldermaston • Reading Barkshire • RG7 APR

25/10/12

Office for Nuclear Regulation Building 4N.2 Redgrave Court Merton Road BOOTLE Merseyside L20 7HS

For the attention of

ONR

Dears

## Suspension of Operations

As you are aware corrosion has been found on a number of the steel structural columns supporting the central section of A## 1. As previously discussed with yourself I have taken the decision to formally implement a suspension of operations in the A## complex.

The facility will continue to undertake activities that maintain the facilities safety arrangements such as safety checks and a series of activities to reduce the current level of risk. This will involve essential maintenance and monitoring activities, as well as waste management and fissile moves leading to a reduction of hazardous inventory. These activities have been authorized by me following facility ALARP review and approval by the Nuclear Safety.

Additionally the facility and project will continue to undertake the necessary work to progress the programme of column remediation. This will include characterization of the state of the columns and eventual repair etc. This project of work is subject to its own separate form of approval and permissioning arrangements.

Control of all work is implemented through the Facility Manager A## and the revised and enhanced local planning and work control procedures. Any change to the authorized activities will be subject to my further authorization. We will ensure via the HPCP that you are aware and content with these further activities prior to their commencement.

Yours sincerely



KW is a financial Crisis of a resource or provide the second for such antical approximation of the second force and force and

