

Table 4.1. Type 3 Trainer Requirements by Location and Type.

	Type 3	Type 3A	Type 3B	Type 3C	Type 3D	Type 3E	WTU-20
Barksdale B61-7				1		1	
Barksdale B83-0				2			
Barksdale W80-1	30	1					
Barksdale WTU-20							12
Cannon B61-4						3	
Minot B61-4						1	
Minot B61-7				2		2	
Minot B83-0				2			
Minot W80-1	2	1					
Minot WTU-20							13
Minot W78-0		2					
Seymour Johnson B61-4						5	
Whiteman B61-4						1	
Whiteman B61-7				2		8	
Whiteman B61-11				1		5	
Whiteman B83-0				2			
Malmstrom W78-0		1					
Malmstrom W62-0				2			
Eglin B61-4		3					
Eglin B61-7				3			
Eglin B83-0				3			
Eglin W62-0				4			
Eglin W78-0		2			1		
Eglin W87-0			2	2			
Eglin W80-1		3			1		
Sheppard B61-4		1				1	
Sheppard B61-7				1		2	
Sheppard B83-0				2			
Sheppard W80-1		1					
Sheppard W78-0		2					
Sheppard W87-0				1			
FE Warren W62-0				1			
FE Warren W87-0				2			
Vandenberg W62-0				2			
Vandenberg W87-0				1			
Aviano B61-4		2				3	

	Type 3	Type 3A	Type 3B	Type 3C	Type 3D	Type 3E	WTU-20
Buechel B61-4		1				6	
Ghedi B61-4		1				6	
Incirlik B61-4		2				1	
Kleine Brogel B61-4		1				6	
Lakenheath B61-4		2				7	
Ramstein B61-0						1	
Ramstein B61-4		2				4	
Spangdahlem B61-4		1				1	
Volkel B61-4		1				6	
Nellis B53-1		1					
Nellis B61-4		2					
Nellis B61-7				1			
Nellis B83-1				1			
Nellis W56-4				1			
Nellis W62-0				1			
Nellis W78-0		1					
Nellis W80-1		1					
Kirtland B61-4		2					
Kirtland B61-7				2			
Kirtland B61-11				1			
Kirtland B83-0				2			
Kirtland W62-0				1			
Kirtland W80-1		1					
Kirtland W84-0		1					
Kirtland W87-0		1	1				

4.1.22. Nuclear weapons storage locations and maintenance bays must contain a thermometer if the types of weapons stored are required to comply with weapon temperature stabilization. This includes weapons storage vaults and weapons maintenance trucks (WMT).

4.1.23. Prohibit use of unauthorized locally manufactured equipment (LME). Unauthorized munitions LME is equipment not authorized by technical data. MAJCOMs must coordinate all LME modifications prior to use. You may perform minor modification of hand tools and fabrication of gauges for non-critical measurements when standard tools prove inadequate to perform required maintenance.

4.2. Nuclear Weapons Deficiency Reporting.

4.2.1. Deficiencies associated with nuclear weapons, nuclear weapon-related items, associated equipment/software or technical orders/publication must be reported.