COMMERCE BUSINESS DAILY ISSUE OF APRIL 9,1999 PSA#2321

Director of Strategic Systems Programs, 1931 Jefferson Davis Hwy, Arlington, VA 22202-3518

12 — TRIDENT II (D5) FIRE CONTROL PRODUCTION AND OPERATIONAL SUPPORT SOL N00030-00-Q-0001 DUE 051799 POC Virginia Hennings, (703) 607-0910 The Contractor shall provide Fire Control Operational Support, Repair, and equipment and materials to: (1) upgrade three SSBN MK 98 MOD 1 Fire Control Systems to MK 4 configuration, (2) upgrade one MK 98 MOD 1 Fire Control System to MK 4 configuration for the Trident Training Facility, (3) upgrade one UK SSBN MK98 Mod 0 Fire Control Systems to Mod 5 configuration, (4) upgrade two UK MK98 Mod 0 Fire Control Systems to Mod 5 configuration. The contractor shall also be required to provide additional years of effort in FY01 and FY02 at the Government's option. Negotiations will be conducted with General Dynamics Defense Systems (GDDS), Pittsfield, MA. GDDS is the sole manufacturer of the FBM fire control system and the only source with the in-depth knowledge and in-place capability to perform the required effort. See Note 22.***** Posted 04/07/99 (W-SN317419), (0097)

Loren Data Corp. http://www.ld.com (SYN# 0172 19990409\12-0002.SOL)

12 - Fire Control Equipment Index Page

System to for

Upgrado (1) 355BN Mh98 Modl Mk & config.

(2) 1 Mh98 Modl Mh & confis the Tritor Facility,

(3) 1 Uk 55BN Mh98 Modo Mod 5 confis

(4) 2 Uh Mh98 Modo Mod 5 config

(4) 2 Uh Mh98 Modo Mod 5 config

-F400; Additional years of effort F701,02, ab hour's oprion