

CONVOY VEHICLE FAULT REPORT

MO No: [REDACTED] DTG: 251630JUL2011 VRN: [REDACTED] Speedometer: N/K

Vehicle Type: TCHD(E) TCHD(L) HSV(E) HSV(L) CSV PEV FFV
RECY COACH TRAFFIC M/C C2V

Usage: Convoy Training Trials

Location: Aldermaston Burghfield Coulport CCL Derby
Other location (specify): I20 M6

Map Ref: Page: Map Grid: Route No: Kelstern:

Symptom(s): Engine stopped.

Fault(s): Low fuel; possible pick-up pipe fault at fuel tank.

Remedy: Fuel level topped up; [REDACTED]

Repaired: On CSV Rest break Staging Roadside
Other (specify): GFG

Discovered: Convoy Loading Training Staging Rest break Trials
Other (specify): GHF

Effect: Nil Head change Trailer change Load transfer Replace vehicle
Recover vehicle

Limitation: Nil Reduce speed Increase speed Alternate route

Job time (mins): 20 Time finish job: 16:50 Delay: YES

Fitter: [REDACTED] Driver: [REDACTED] Recovery to: N/A

Follow-up action

Workshop Job No: U01852 Fault Report No: N/A Defect Signal No: N/A

Warranty Repair: NO Mod in progress: NO